

Upper Village Road - Site #2

Work to be performed:

North of Boardmans. Repair slope.

Dimensions:

Length Along Road:	30 Feet
Width Along Slope	10 Feet
Ditch Width:	0 Feet
Stone Depth:	4 Feet
Roadway Width:	0 Feet

Culvert Quantities:

Culvert:	0.0	LF	Cost of all excavation and roadway material for installation.
----------	-----	----	---

Ditch Quantities:

Excavation:	0.0 CY
Stone Fill, Type 1:	0.0 CY
1 - 1/2" Crushed Stone	0.0 CY

Slope Quantities

Excavation:	44.4 CY
Stone Fill, Type II	44.4 CY

Roadway Quantities:

Roadway Material - 1-1/4" Plant Mix	0.0 CY
-------------------------------------	--------