## South Washington Road - Site #2

## Work to be performed:

Second site north of Upper Village Road, right side of road. Repair slope at brook. Steep embankment, use stone toe wall detail.

**Dimensions:** 

Length Along Road: 60 Feet Width Along Slope 10 Feet Ditch Width: 0 Feet Stone Depth: 4 Feet Roadway Width: 0 Feet

**Culvert Quantities:** 

Cost of all excavation and Culvert:

0.0

LF

roadway material for installation.

Ditch Quantities:

Excavation: 0.0 CY
Stone Fill, Type 1: 0.0 CY
1 - 1/2" Crushed Stone 0.0 CY

Slope Quantities

Excavation: 88.9 CY
Stone Fill, Type IV 88.9 CY

**Roadway Quantities:** 

Roadway Material - 1-1/4" Plant Mix 0.0 CY