

Edwards Road - Site #4

Work to be performed:

Repair slope

Dimensions:

Length Along Road: 50 Feet

Width Along Slope 10 Feet

Stone Depth: 20 Feet

Slope Quantities

Stone Fill, Type IV 370.0 CY

Contractor to provide and haul material