

Brook Road - Site #3

Work to be performed:

By Button Farm. Repair/reestablish ditch. Town to supply and haul material.

Dimensions:

Length Along Road:	150.0 Feet
Width Along Slope	0.0 Feet
Ditch Width:	6.0 Feet
Stone Depth:	2.0 Feet

Ditch Quantities:

Excavation:	33.3 CY
Stone Fill, Type 1:	33.3 CY
1 - 1/2" Crushed Stone	16.7 CY

Slope Quantities

Excavation:	0.0 CY
Stone Fill, Type II	0.0 CY