

## Brook Road - Site #4

### Work to be performed:

East side of road, south of Pent Road. Repair of uphill slide area and reestablish ditch.

### Dimensions:

Length Along Road:	75.0 Feet
Width Along Slope	20.0 Feet
Ditch Width:	6.0 Feet
Stone Depth:	2.0 Feet

### Ditch Quantities:

Excavation:	16.7 CY
Stone Fill, Type 1:	16.7 CY
1 - 1/2" Crushed Stone	8.3 CY

### Slope Quantities

Excavation:	111.1 CY
Stone Fill, Type II	111.1 CY