

## Brook Road - Site #5

### Work to be performed:

North of Pent Road, east side of road. Repair/reestablish ditch.  
Town to supply and haul material.

### Dimensions:

Length Along Road:	300.0 Feet
Width Along Slope	0.0 Feet
Ditch Width:	6.0 Feet
Stone Depth:	0.0 Feet

### Ditch Quantities:

Excavation:	66.7 CY
Stone Fill, Type 1:	66.7 CY
1 - 1/2" Crushed Stone	33.3 CY

### Slope Quantities

Excavation:	0.0 CY
Stone Fill, Type II	0.0 CY